Arborist Report
Harbor Bay Parkway- Tree #39

Date: July 8, 2016

To: Liam Garland, Acting Public Works Director
950 West Mall Square, Room 110
Alameda, CA 94501

Subject: Harbor Bay Parkway Tree

Location: South Loop near HBP

Species: Alnus Rhombifolia- White Alder (DBH-16")

Recommendation: Removal – Dead Tree

Summary: Tree mortality was caused by an infestation of the Flatheaded Alder Borer (Agrilus burkei) brought on by overall stress in the tree due to its growing in shallow and sandy soil. The tree is dead and should be removed. There is no urgent safety threat. The tree was inspected on July 7, 2016.



Prepared by:

Marshall F Lyons The Forestree Company
WCISA Certified Arborist # WE-5796A

1207 Peralta Av.
Berkeley, CA 94706
Phone & Fax: (510) 528-8060
E-mail: forestree@lmi.net