

Arborist Report
1514 8th Street

Date: August 5, 2013

To: Bob Haun, Interim Public Works Director
950 West Mall Square, Room 110
Alameda, CA 94501


Subject: 1514 8th Street

Species: Brachychiton populaneus- Bottle Tree

Recommendation: Removal – Hazardous Tree

Summary: The tree is significantly damaged and suffering from extensive root rot disease. It poses a safety risk to the general public and/or private property and should be removed. There is an urgent safety threat. The tree was inspected on August 5, 2013.

Photo:



Prepared by:


Jesse Barajas, EMPA Public Works Superintendent
WCISA Certified Arborist # 4394A
Qualified Applicator/ DPR # 91794

1616 Fortmann Way
Alameda, CA 94501
Phone (510) 747-7924, Fax (510) 521-8762
E-mail: jbarajas@ci.alameda.ca.us